



# TECHNotes

Marathon Equipment has made the following changes to accommodate product improvements. Please note these changes and keep for future reference. For a complete list of Tech Notes, product information and news from Marathon, log-on to our web site:

[www.MarathonEquipment.com/TechNotes.htm](http://www.MarathonEquipment.com/TechNotes.htm)

If you have a service, maintenance or technical question, email our Service Department Manager:  
Keith@marathonequipment.com

Or call: **1-800-633-8974** and ask for anyone in Field Service.:

**Marathon Equipment Company  
Technical Bulletin #146-02  
Effective: November 2002**

### **Machines Effected:**

RJ-1835, RJ-1835-5A, RJ-1835-3A, 2 yard front & rear load 1835 containers

### **Improvement:**

This TechNote changes the design of the RJ-1835 horizontal compactor to have a **single ratchet** with **bottom hook-up** to the container. This feature is now standard on all RJ-1835 units and eliminates the need for the single ratchet option. The ratchet will be mounted on the same side as the controls unless otherwise noted on the order.